Division of Health Care Facilities STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION IDENTIFICATION NUMBER: (X3) DATE SURVEY A. BUILDING: 02 - BOULEVARD TERRAACE NURSING COMPLETED HOME TN7502 B. WING 01/04/2016 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 1530 MIDDLE TENNESSEE BLVD BOULEVARD TERRACE REHABILITATION AND MURFREESBORO, TN 37130 SUMMARY STATEMENT OF DEFICIENCIES (X4) ID PROVIDER'S PLAN OF CORRECTION (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (X5) COMPLETE PREFIX (EACH CORRECTIVE ACTION SHOULD BE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG CROSS-REFERENCED TO THE APPROPRIATE TAG DATE DEFICIENCY) N 848 1200-8-6-.08 (18) Building Standards N 848 N 848 (18) It shall be demonstrated through the 1. The negative air pressure vent in submission of plans and specifications that in the bathroom of A/B nurses station will each nursing home a negative air pressure shall be fixed by February 6, 2016 by the be maintained in the soiled utility area, toilet maintenance department. room, janitor 's closet, dishwashing and other 2. Soiled utility areas, toilet rooms, such soiled spaces, and a positive air pressure janitor closest, dishwashing and other shall be maintained in all clean areas including. soiled spaces were inspected by the but not limited to, clean linen rooms and clean maintenance department on 1-14-16 utility rooms. and all were found to be working properly. 3. Education was done on 1-14-16 by the Administrator with the This Rule is not met as evidenced by: maintenance department regarding the Based on observations the facility failed to regulation that negative air pressure maintain exhaust systems. 02-06-16 shall be maintained in the soiled utility area, toilet room janitor's closet, The findings included: dishwashing and other such soiled spaces, and a positive air pressure Observation on 1/4/2016 at 10:17 AM, revealed shall be maintained in all clean areas negative air pressure was not maintained in staff including clean linen rooms and clean bathroom located inside the A/B nurses station. utility rooms. NFPA 101, 19.5.2.1 (2000 Edition) 4. The Director of Maintenance or designee will ensure that rooms This finding was verified by the director of maintenance and acknowledged by the required to have negative air pressure are working weekly x 4 weeks and administrator during the exit conference on then monthly afterwards on a 1/4/2016 preventative maintenance program. 5. February 6, 2016

Division of Health Care Facilities

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

nellla STATE FORM

(X6) DATE

1-14-16 If continuation sheet 1 of 1